



MAR 25 2026

ND DEPT. OF WATER RESOURCES

Department of Water Resources • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the Department of Water Resources within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No												
Name Hamlin Water				Was Well Disinfected Upon Completion? ☒ Yes ☐ No												
Address 5031 141st Ave NW Williston, ND 58801				WATER LEVEL												
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface 52												
		County Williams		GPS		If Flowing, Closed-In Pressure In PSI N/A										
		1/4 SW	1/4 NW	1/4	GPM Flow _____ Through _____ Inch Pipe											
		Township 154N	Range 96W	Section 17	Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____											
PROPOSED USE 15409617-5C				WELL TEST DATA												
☐ Domestic ☐ Geothermal ☐ Municipal ☒ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☒ Pump ☐ Bailor ☐ Other												
METHOD DRILLED				Pumping Level Below Land Surface												
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				<table border="1" style="width: 100%;"> <tr> <td>88 Feet After</td> <td>12 Hrs. Pumping</td> <td>420 GPM</td> </tr> <tr> <td>Feet After</td> <td>Hrs. Pumping</td> <td>GPM</td> </tr> <tr> <td>Feet After</td> <td>Hrs. Pumping</td> <td>GPM</td> </tr> </table>				88 Feet After	12 Hrs. Pumping	420 GPM	Feet After	Hrs. Pumping	GPM	Feet After	Hrs. Pumping	GPM
88 Feet After	12 Hrs. Pumping	420 GPM														
Feet After	Hrs. Pumping	GPM														
Feet After	Hrs. Pumping	GPM														
WATER QUALITY Was a water sample collected for				WELL LOG												
Chemical Analysis? ☒ Yes ☐ No				Formation												
Bacteriological Analysis? ☐ Yes ☐ No				Depth (ft.)												
If So, To What Laboratory Was It Sent? Astro-Chem, Williston, ND				From To												
WELL CONSTRUCTION																
Diameter Of Hole In Inches 20"		Depth In Feet 135														
Casing:																
☒ Steel ☐ Plastic ☐ Concrete ☐ Other ☐ Threaded ☒ Welded ☐ If Other, Specify _____																
Pipe Weight lb/ft	Diameter inches	From feet	To feet													
54.7	14	+2	90													
Was A Well Screen Installed? ☒ Yes ☐ No																
Was Perforated Pipe Used? ☐ Yes ☒ No																
Screen Or Perforation Interval		From In Feet	To In Feet													
Was Casing Left Open End? ☐ Yes ☒ No																
Material Stainless Steel Screen		Diameter In Inches 20" 14"														
Slot Size #70	Set From In Feet 90	To In Feet 120														
Sot From In Feet		To In Feet														
DATE COMPLETED 6-27-2025																
Was Packer Or Seal Used? ☐ Yes ☒ No				WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No												
If So, What Material		Depth In Feet		If So, How												
Type Of Well ☐ Straight Screen ☒ Gravel Packed				REMARKS												
Depth Grouted Bentonite Chips	0	From	To													
Grouting Material	Cement		Other													
If Other, Explain:																
Well Head Completion: Pitless Unit Yes				DRILLER'S CERTIFICATION												
12" Above Grade Yes		Other (Specify)		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.												
It Other, Specify				Driller's Or Firm's Name Agn Industries Inc.		License Number 123										
Address 3105 2nd St West, Williston, ND 58801				Date 10 July 2025												

COPY FOR DWR

COPY FOR DRILLER

COPY FOR CUSTOMER