



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

DEC 23 2025

NO DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <i>Matt Larson</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>Milnor ND</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>6.9</i>			
				County <i>Ransom</i> GPS <i>46.37711</i>			
				1/4 <i>97</i> 1/4 <i>45</i> 1/4 <i>105</i>			
				Township Range Section			
PROPOSED USE <i>13405434DAB</i>				GPM Flow Through Inch Pipe			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial				Controlled By ☐ Valve ☐ Reducers ☐ Other			
☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ If Other, Specify _____			
METHOD DRILLED				WELL TEST DATA			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary				☒ Pump ☐ Bailer ☐ Other			
☐ Bored ☐ Auger ☐ If Other, Specify _____				Pumping Level Below Land Surface			
WATER QUALITY Was a water sample collected for				Feet After <i>13.8</i> Hrs. Pumping <i>1</i> GPM <i>10</i>			
Chemical Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
If So, To What Laboratory Was It Sent?				WELL LOG			
WELL CONSTRUCTION				Formation Depth (ft.)			
Diameter Of Hole In Inches <i>9</i> Depth In Feet <i>25 18 1/2</i>				From To			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other				<i>Top</i> <i>0</i> <i>2</i>			
☐ Threaded ☐ Welded ☐ If Other, Specify _____				<i>Med Brown sand</i> <i>2</i> <i>10</i>			
Pipe Weight Diameter From To				<i>Coarse gray</i> <i>10</i> <i>18 1/2</i>			
<i>SDR-21</i> <i>5</i> <i>-1 1/2</i> <i>13 1/2</i>				<i>sand + gravel</i>			
lb/ft inches feet feet				<i>Looking alot lighter</i>			
<i>18 1/2</i> <i>25</i>				<i>gray clay</i> <i>18 1/2</i> <i>25</i>			
Was A Well Screen Installed? ☒ Yes ☐ No							
Was Perforated Pipe Used? ☐ Yes ☒ No							
Screen Or Perforation Interval From In Feet To In Feet							
Was Casing Left Open End? ☐ Yes ☒ No							
Material <i>SDR-21</i> Diameter In Inches <i>5</i>							
Slot Size <i>.50</i> Set From In Feet <i>13 1/2</i> To In Feet <i>18 1/2</i>							
Slot Size Set From In Feet To In Feet							
Was Packer Or Seal Used? ☐ Yes ☒ No				Use Separate Sheet If Necessary			
If So, What Material Depth In Feet				DATE COMPLETED <i>11-20-25</i>			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Depth Grouted From <i>0</i> To <i>10</i>				If So, How			
Grouting Material Cement Other				REMARKS			
If Other, Explain: <i>Bentonite chips</i>							
Well Head Completion: Pitless Unit <i>yes</i>				DRILLER'S CERTIFICATION			
12" Above Grade <i>yes</i> Other (Specify)				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
It Other, Specify				Driller's Or Firm's Name <i>MSW Drilling</i> Certificate Number <i>92</i>			
				Address <i>Oakes ND</i>			
				Signed By <i>Wayne Doty</i> Date <i>11-15-25</i>			