



WELL DRILLER'S REPORT
NORTH DAKOTA DEPARTMENT OF WATER RESOURCES
WATER APPROPRIATION
SFN 60273 (7/2025)

RECEIVED

JUN 02 2026

Department of Water Resources • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the Department of Water Resources within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☐ No			
Name Bill Buckman				Was Well Disinfected Upon Completion? ☐ Yes ☐ No			
Address				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface 46			
		County Golden Valley		GPS		If Flowing, Closed-In Pressure In PSI	
		1/4 NE		1/4 SW		GPM Flow Through Inch Pipe	
		Township 140		Range 103		Controlled By ☐ Valve ☐ Reducers ☐ Other	
		Section 30				☐ If Other, Specify _____	
PROPOSED USE 14010330BCA				WELL TEST DATA			
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial				☒ Pump ☐ Bailer ☐ Other			
☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				Pumping Level Below Land Surface			
METHOD DRILLED				Feet After Hrs. Pumping GPM			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary				140 1 10			
☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After Hrs. Pumping GPM			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☐ No				WELL LOG			
Bacteriological Analysis? ☐ Yes ☐ No				Formation Depth (ft.)			
If So, To What Laboratory Was It Sent?				From To			
WELL CONSTRUCTION				Brown clay 0 26			
Diameter Of Hole In Inches 8.75		Depth In Feet 408		Brown sand 26 35			
Casing:				Gray clay coal and sand stringers 35 118			
☐ Steel ☒ Plastic ☐ Concrete ☐ Other				coal 118 123			
☐ Threaded ☐ Welded ☐ If Other, Specify _____				Clay 123 126			
Pipe Weight	Diameter	From	To	Sand 126 131			
lb/ft 3.8	5 inches	+2 feet	388 feet	Clay and sand stringers 131 369			
lb/ft	inches	feet	feet	Sand fine 369 380			
lb/ft	inches	feet	feet	Sand medium 380 412			
Was A Well Screen Installed? ☒ Yes ☐ No				clay 410 418			
Was Perforated Pipe Used? ☐ Yes ☐ No							
Screen Or Perforation Interval	From In Feet	To In Feet					
	388	408					
Was Casing Left Open End? ☐ Yes ☐ No							
Material PVC	Diameter In Inches 5			Use Separate Sheet If Necessary			
Slot Size 25	Set From In Feet 388	To In Feet 408		DATE COMPLETED 5-30-26			
Slot Size	Set From In Feet	To In Feet		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☐ No			
Was Packer Or Seal Used? ☐ Yes ☐ No				If So, How			
If So, What Material		Depth In Feet		REMARKS			
Type Of Well ☐ Straight Screen ☐ Gravel Packed				46.9147717,-103.7310259			
Depth Grouted	From	To		DRILLER'S CERTIFICATION			
0		320		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
Grouting Material	Cement	Other		Driller's Or Firm's Name Brase Drilling License Number 179			
If Other, Explain:				Address 2813 Hwy 2 west Rugby ND 58368			
Well Head Completion: Pitless Unit				Signed By Ben Brase Date 6-2-26			
12" Above Grade		Other (Specify)					
If Other, Specify							