WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED
JUN 04 2026
ND DEPT OF WATER RESOURCES

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND 58504
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER
Name: RYAN HENDRICKSON
Address:

WELL LOCATION Sketch map location must agree with written location.
County: MORTON | GPS: BOTTOM
1/4 | 1/4 | 1/4
Township | Range | Section

PROPOSED USE 1400822 CBC
☑ Domestic ☑ Stock ☐ Geothermal ☑ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

METHOD DRILLED
☑ Cable ☐ Bored ☐ Jetted ☐ Auger ☑ Forward Rotary ☐ If Other, Specify ☐ Reverse Rotary

WATER QUALITY Was a water sample collected for
Chemical Analysis? ☑ Yes ☐ No
Bacteriological Analysis? ☑ Yes ☐ No
If So, To What Laboratory Was It Sent? MVTL

WELL CONSTRUCTION
Diameter Of Hole In Inches: 7 7/8 | Depth In Feet: 178
Casing: ☐ Steel ☑ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify

Pipe Weight	Diameter	From	To
lb/ft SCH 40	inches 4	feet 0	feet 158
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was A Well Screen Installed? ☑ Yes ☐ No
Was Perforated Pipe Used? ☐ Yes ☑ No
Screen Or Perforation Interval: 16 SLOT | From In Feet | To In Feet
Was Casing Left Open End? ☐ Yes ☑ No
Material: PVC | Diameter In Inches: 4

Slot Size	Set From In Feet	To In Feet
16	158	178
Slot Size	Set From In Feet	To In Feet

Was Packer Or Seal Used? ☐ Yes ☑ No
If So, What Material | Depth In Feet
Type Of Well ☐ Straight Screen ☑ Gravel Packed #40

Depth Grouted	From	To
	30	0
Grouting Material: MEDIUM CHIPS	Cement	Other

If Other, Explain:
Well Head Completion: Pitless Unit YES
12" Above Grade YES | Other (Specify)
It Other, Specify

Was Pump Installed? ☑ Yes ☐ No
Was Well Disinfected Upon Completion? ☑ Yes ☐ No

WATER LEVEL
Static Water Level (In Feet) Below Surface: P.S. 121'
If Flowing, Closed-In Pressure In PSI
GPM Flow | Through | Inch Pipe
Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify

WELL TEST DATA
☑ Pump ☐ Bailer ☐ Other
Pumping Level Below Land Surface

Feet After	Hrs. Pumping	GPM
140	2hrs	7
Feet After	Hrs. Pumping	GPM
Feet After	Hrs. Pumping	GPM

WELL LOG

Formation	Depth (ft.) From	To
TOP SOIL	0	2
GREY CLAY	2	9
ROCK / SHALE?	9	11
BROWN CLAY	11	25
GREY CLAY	25	39
SHALE	39	40
GREY CLAY	40	85
HARD SANDY CLAY	85	91
SAND STONE	91	93
SANDY CLAY / DARK GREY	93	109
SAND STONE	109	110
GREY CLAY	110	141
SAND STONE	141	143
GREY SANDY CLAY	143	161
SAND STONE	161	163
GREY CLAY	163	170
BLUE BLACK SAND/FINE	170	177
CASED	177	178

Use Separate Sheet If Necessary

DATE COMPLETED
WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☐ No
If So, How

REMARKS
GPS 46° 54' 43.9" N
101° 00' 24.4" W

DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.
Driller's Or Firm's Name: Northern Plains Drilling | Certificate Number: 127
Address: 4007 STATE ST SUITE 40
Signed By: [signature] | Date: 5/27/2026

COPY FOR BOARD COPY FOR DRILLER COPY FOR CUSTOMER