



WELL DRILLER'S REPORT

NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS

STATE OF NORTH DAKOTA

SFN 60273 (8/2020)

Received by email

July 2, 2026

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER		Was Pump Installed? ☐ Yes ☒ No	
Name Andy Stoltzfus		Was Well Disinfected Upon Completion? ☒ Yes ☐ No	
Address Black River Falls, WI		WATER LEVEL	
WELL LOCATION Sketch map location must agree with written location.		Static Water Level (In Feet) Below Surface NA	
	County Bowman	GPS 45.975556, -103.378333	
	1/4 SW	1/4 SW	1/4 SE
	Township 129N	Range 102W	Section 24
PROPOSED USE 12910224DCC		WELL TEST DATA	
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☒ Irrigation ☐ Monitoring ☐ Test Hole		☐ Pump ☐ Bailer ☐ Other _____	
METHOD DRILLED		Pumping Level Below Land Surface	
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____		Feet After Hrs. Pumping GPM	
WATER QUALITY Was a water sample collected for		Feet After Hrs. Pumping GPM	
Chemical Analysis? ☐ Yes ☒ No		Feet After Hrs. Pumping GPM	
Bacteriological Analysis? ☐ Yes ☒ No		WELL LOG	
If So, To What Laboratory Was It Sent?		Formation Depth (ft)	
WELL CONSTRUCTION		From To	
Diameter Of Hole In Inches 6-1/4" Depth In Feet 201'		top soil 0 1	
Casing: ☐ Steel ☐ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____		sand 1 9	
Pipe Weight lb/ft	Diameter inches	From feet	To feet
Was a Well Screen Installed? ☐ Yes ☐ No		clay 9 19	
Was Perforated Pipe Used? ☐ Yes ☐ No		coal 19 19.5	
Screen Or Perforation Interval From In Feet To In Feet		clay 19.5 23	
Was Casing Left Open End? ☐ Yes ☐ No		hard white sand 23 24	
Material Diameter In Inches		clay 24 28	
Slot Size	Set From In Feet To In Feet	silty sand 28 30	
		silty clay 30 31	
		clay 31 37	
		coal 37 41.5	
		silty clay 41.5 44	
		silt 44 45	
		clay 45 54	
		bentonitic clay 54 56.5	
		coal 56.5 59	
		clay 59 60	
Use Separate Sheet If Necessary		See Additional details listed on attached sheet.	
DATE COMPLETED 6/29/26		WAS WELL PLUGGED OR ABANDONED? ☒ Yes ☐ No	
Was Packer Or Seal Used? ☐ Yes ☐ No		If So, How Plugged well w/ drill cuttings.	
If So, What Material Depth In Feet		REMARKS	
Type Of Well ☐ Straight Screen ☐ Gravel Packed	Exploration hole was drilled to 201' with 6-1/4" exploration bit. (Continued on attached sheet.)		
Depth Grouted From To	DRILLER'S CERTIFICATION		
Grouting Material Cement Other	This well was drilled under my jurisdiction and this report is true to the best of my knowledge.		
If Other, Explain:	Driller's Or Firm's Name Bedrock Drilling LLC Certificate Number 197		
Well Head Completion: Pitless Unit	Address PO Box 248, Rhame, ND 58651		
12" Above Grade Other (Specify)	Signed By <i>[Signature]</i> Date 7/1/26		
If Other, Specify			

Completion Date: 6/29/26

REMARKS (continued)
This is the 3rd of 3 wells in this section that we drilled. The other 2 wells had water above 40'. We did not see any water in this well until 71'. In this section, the north well was the best. The middle well was of lesser quality. While it had very minor water in the silt from 71' to 80', this well was not of sufficient quantity to run screens and casing. Land owner has requested that we move north and try again. Sanitized well and plugged and abandoned well with drill cuttings.