



WELL DRILLER'S REPORT
NORTH DAKOTA DEPARTMENT OF WATER RESOURCES
WATER APPROPRIATION
SFN 60273 (7/2025)

RECEIVED

AUG 17 2026

ND DEPT. OF WATER RESOURCES

Department of Water Resources • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the Department of Water Resources within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name Enderlin Park District				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address PO Box 134 Enderlin, ND 58027				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface 10.2			
		County Ransom	GPS See Remarks			If Flowing, Closed-In Pressure In PSI	
		1/4 NE	1/4 NE	1/4 NW		GPM Flow Through Inch Pipe	
		Township 136	Range 55	Section 4		Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____	
PROPOSED USE 13605504 ARB				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☒ Irrigation ☐ Monitoring ☐ Test Hole				☒ Pump ☐ Bailer ☐ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After Hrs. Pumping GPM			
WATER QUALITY Was a water sample collected for				11 4 3/4 40			
Chemical Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
If So, To What Laboratory Was It Sent?				WELL LOG			
WELL CONSTRUCTION				Formation Depth (ft.)			
Diameter Of Hole In Inches 7 7/8		Depth In Feet 190		From		To	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☒ Welded ☐ If Other, Specify _____				Top Soil 0 2			
Pipe Weight	Diameter	From	To	Clay w/ lenses of gravel 2 6			
2.96 lb/ft	5 inches	+2 feet	11 feet	Gravel 6 16			
				Sandy Clay 16 65			
				Sandy clay w/ lenses of sand 65 71			
				Sandy Clay 71 86			
				Sand 86 87			
				Sandy Clay 87 102			
				Sand 102 103			
				Sandy Clay 103 147			
				Silty sandy clay 147 190			
Was A Well Screen Installed? ☐ Yes ☒ No							
Was Perforated Pipe Used? ☐ Yes ☒ No							
Screen Or Perforation Interval		From In Feet	To In Feet				
Was Casing Left Open End? ☐ Yes ☒ No							
Material Stainless Steel		Diameter In Inches 4		Use Separate Sheet If Necessary			
Slot Size .020	Set From In Feet 11	To In Feet 16					
Slot Size	Set From In Feet	To In Feet					
Was Packer Or Seal Used? ☐ Yes ☒ No				DATE COMPLETED			
If So, What Material		Depth In Feet		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☐ No			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				If So, How			
Depth Grouted 7	From 0	To 7		REMARKS			
Grouting Material Bentonite	Cement	Other		Open hole was filled with sand and bentonite chips to 18 feet. GPS 46.629075 -97.605243			
If Other, Explain:				DRILLER'S CERTIFICATION			
Well Head Completion: Pitless Unit				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
12" Above Grade X		Other (Specify)		Driller's Or Firm's Name LTP Enterprises, Inc		License Number 136	
If Other, Specify				Address PO Box 9035, Fargo ND 58106		Date 8/10/2026	
				Signed By Chris Ransom			